

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**


*Fig. 1*






Inventor(s): Shinji HAYASHI  
DOCKET NO.: 086142-0655

*Fig. 3*




**Fig. 4**




Inventor(s): Shinji HAYASHI  
DOCKET NO.: 086142-0655

**Fig. 5**




**Fig. 6**



Title: AIRBAG MODULE AND  
MODULE COVER

Inventor(s): Shinji HAYASHI  
DOCKET NO.: 086142-0655

*Fig. 7*



*Fig. 8*

